

# MHC KENWORTH

3331 Greig Drive  
 Robinson, TX 76706  
 254-662-2100

# SERVICE ESTIMATE

**62**

NAME: Kenan  
 ADDRESS: \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 FAX #: \_\_\_\_\_  
 PHONE #: \_\_\_\_\_

DATE: 4/25/2024

INSURANCE CO.: \_\_\_\_\_  
 INS. CO. PHONE #: \_\_\_\_\_  
 ADJUSTERS: \_\_\_\_\_

LICENSE #:	
UNIT #:	<b>1116065</b>
YEAR:	<b>2017</b>
MAKE:	<b>Kenworth</b>
MODEL:	<b>T880</b>
SERIAL #:	<b>HJ163975</b>
MILEAGE:	<b>562180</b>
ENGINE MODEL:	
ENGINE SERIAL#:	
TRANS. MODEL:	
TRANS. SERIAL #:	
REAR END MODEL:	
REAR END SERIAL #:	

QUANTITY		WORK TO BE DONE / PART DESCRIPTION	LABOR COST	PARTS EACH	PARTS TOTAL	SUBLET
REPAIR	REPLACE					
1		Tow disabled	\$77.13			
	1	Strap kit		\$27.82	\$27.82	
1		Check and advise on possible turbo failure.	\$154.25			
1		Tech has confirmed the turbo has failed and has pushed oil into the DOC, DPF and SCR. will need to replace all failed/ contaminated parts and clean all oil residue out of the exhaust.				
	1	Parts list attached.		\$15,777.31	\$15,777.31	
1		Remove and replace the turbo.	\$771.25			
1		Remove and replace the DPF, DOC and SCR and clean any oil residue out of CAC/ exhaust piping.	\$925.50			
1		While inspection over the unit the tech also noted the rocker box is leaking oil. Will need to remove and reseal the rocker box.	\$462.75			
1		Regen and test drive to verify no further issues.	\$231.38			

It is agreed and understood that the above is an estimate only based on visual inspection. Estimate is only good for 90 days. The total estimate figure is subject to change or adjustment due to parts, price changes, or incorrect part numbers, and labor is subject to adjustment for any hidden damage or open items. Air freight will be paid by the customer.

All sales and repairs are cash unless prior arrangements have been made by the credit department. Payment is due and payable five working days after completion of the job.

<b>TOTAL LABOR</b>		\$2,622.25
<b>TOTAL PARTS</b>		\$15,805.13
<b>MISCELLANEOUS</b>		\$314.67
<b>FREIGHT</b>		\$150.00
<b>TOTAL SUBLET REPAIRS</b>		
<b>SALES TAX</b>	8.25%	\$1,329.88
<b>GRAND TOTAL</b>		\$20,221.93

ESTIMATED BY \_\_\_\_\_  
 ASSOCIATED REPAIR ORDER NUMBER: \_\_\_\_\_