

Performance Peterbilt of West Florida

3067 Main Street Cottondale, Florida 32431
Phone: (850) 352-9901



Case Number: 14581432

Repair Order Number: 511258

Purchase Order Number: N/A

Service Advisor: Service, Cottondale - Case Date 2024-01-18 17:22:26 -0500

ETR: 1/26/2024 at 06:00 pm EST

Customer: Kenan Advantage Spg Reynolds,
Ga

Unit Number: 2212216

Address: 303 SOUTH WINDSTON ST
REYNOLDS, GA 31076
Phone: (478) 847-4178
Fax: N/A
Customer Number: 60104

Asset: 2016 Peterbilt 579
Serial Number: GD359674
VIN: 1XPBDP9X5GD359674
Engine: MX-13

Engine Hours: 29415
Odometer: 587218 Miles
Warranty Start: 2016-01-29 12:00:00 -0500
In Service: 8 Years 1 Month

Item	Operation Name	Labor Hours	Hourly Rate	Parts	Additional Charges	Totals
1	TRIAGE AND TRUCK SYSTEMS DIAGNOSTICS					
	Labor:	0	\$205.00			\$0.00
2	Rapid Check (Triage) 1.0 Complaint: CHECK AND ADVISE. CEL, UNIT WILL NOT RUN					
	Labor:	2	\$205.00			\$410.00
3	Fuel filter change Complaint: REPLACE PRIMARY AND SECONDARY FILTER AND ENGINE AIR FILTER					
	Labor:	1	\$205.00			\$205.00
	Parts:					\$330.51
	-(1.0) SEPERATOR-FUEL FILTER			\$42.52		\$42.52
	-(1.0) FILTER-FUEL			\$81.81		\$81.81
	-(1.0) PACCAR AIR FILTER			\$206.18		\$206.18
4	NOX SENSOR REPLACEMENT SINGLE / / Complaint: REPLACE NOX SENSOR					
	Labor:	4.5	\$205.00			\$922.50
	Parts:					\$755.62
	-(1.0) SENSOR-NOX REMAN			\$755.62		\$925.62
5	Pressure Test Cooling system Complaint: LOWER COOLANT HOSE LEAKING , AUX COOLER HOSE TO APU LEAKING CHAFFING ON ENGINE WIRING HARNESS					
	Labor:	2	\$205.00			\$410.00
	Parts:					\$83.23
	-(1.0) COOLANT-TRP ELC 50/50 JUG			\$14.70		\$14.70
	-(1.0) HOSE-RADIATOR #40 1 PICK=			\$38.01		\$38.01
	-(10.0) CABLE TIE 11"			\$0.87		\$8.70
	-(2.0) CLAMP-CONSTANT TORQUE #44			\$10.91		\$21.82
6	STEER SPRING PINS R&R Complaint: SPRING PIN BUSHINGS ARE OUT OF SPEC, EXCESSIVE PLAY					
	Labor:	11	\$205.00			\$2,255.00
	Parts:					\$1,434.38
	-(4.0) BUSHING-PIN SPRING			\$38.61		\$154.44

Performance Peterbilt of West Florida

Customer: Kenan Advantage Spg Reynolds, Ga	Unit Number: 2212216
Case Number: 14581432	Asset: 2016 Peterbilt 579 VIN: 1XPBDP9X5GD359674

Item	Operation Name	Labor Hours	Hourly Rate	Parts	Additional Charges	Totals
-(2.0)	BRACKET ASSY-SHACKLE W/THEADED BUSHING			\$464.73		\$929.46
-(4.0)	LINK-SHACKLE			\$71.42		\$285.68
-(8.0)	BOLT M12 X 70MM			\$5.25		\$42.00
-(8.0)	NUT-HEX SL NYL M12-1.75X14.40T CL10 CAD			\$2.85		\$22.80

Parts: \$2,603.74
Labor: \$4,202.50
Shop Supplies: \$630.38
Haz. Waste: \$130.19
Taxes: \$580.26
Core: \$170.00
Total: \$8,317.07

Notes:

[1/18/2024 at 05:37 pm EST] - UNIT CHECKED IN
 [1/18/2024 at 05:38 pm EST] - Approval Requested for the estimate version 1. View the estimate. NOTE: REQUESTING AUTHORIZATION FOR DIAGNOSTICS
Repair status set to Hold (auth).
 [1/19/2024 at 08:40 am EST] - approved per estimate of \$506.86. please advise and estimate for approval for any further repairs
 [1/22/2024 at 08:01 am EST] - Good Morning West Florida Service Team, may we please have an update on this unit?
 [1/22/2024 at 03:03 pm EST] - WAITED ON BAY SPACE TO BECOME AVAILABLE, WE NOW HOW TRUCK IN SHOP AND DIAG IN PROGRESS
 [1/24/2024 at 11:55 am EST] - Approval Requested for the estimate version 2. **Total \$8,317.07.**
 View the estimate.
 NOTE: Please see the attached estimate. there is a few things that we found and recommend replacing. please advise. Thank you.
Repair status set to Hold (auth).

All Credit Card transactions will be charged a 3.5% fee. Cash, Company Check, or ACH will be gladly accepted. This estimate is subject to teardown and inspection and is valid for 30 days from date above. I, the undersigned, authorize you to perform the repairs and furnish the necessary materials. I understand any costs verbally quoted are an estimate only and not binding. Your employees may operate vehicle for inspecting, testing and delivery at my risk. You will not be responsible for loss or damage to vehicle or articles left in it. I understand that a storage charge equal to \$75.00 will be assessed and shall accrue daily if I fail to pick up the vehicle within 3 working days after being notified that the repairs have been completed. AUTHORIZED
 BY: _____ DATE: ___/___/___